

Due to the increasing number of customers questioning the release of the Service Bulletin No. 03/07/2011 we would like to state the following:

- The reason for issuing the SB was repeated findings of using Main Risers that are no longer suitable.
- The reason for the unsuitability of using Main Risers is not their technical problems but usual wear.
- The issue was described in the SB since it is not being solved in the relevant technical documentation.
- When defining the limits in the SB, we applied our own experience in the operation and also limits defined by manufacturers in abroad.