



MarS a.s., Okružní II. čp. 239, 569 43 Jevíčko

**SERVICE
BULLETIN**

C Z E C H R E P U B L I C

SERVICE BULLETIN No. 5/07/2004

INSPECTION OF STUDENT-TYPE HARNESSSES

- 1. APPLICABLE TO:** STUDENT-type harnesses marked as PS – 034 S
with a production date from **20.10. 2001** onward
- 2. REASON:** Possible seam damage (in chest harness straps).
- 3. MEASURES:**
 - A) To regularly inspect the possible damage of load-bearing seams in the are of the sowing of chest straps (left and right, face and reverse side).
 - B) To carry out strict inspections of proper outfitting prior to a jump, mainly focusing on:
 - the appropriate regulation of the size of the harness depending on the height of the parachutists
 - the proper leading of the straps on the parachutist's body (especially with regard to the possible twisting and twirling of the straps).
- 4. COMPLETION PERIOD:** Repeatedly before using the parachute
- 5. COSTS ARE BORNE BY:** It depends on the results of the inspections.
The repair of possible damage will be provided at the manufacturer's expense.
- 6. REQUIRED MATERIAL:** Material for possible repair will be arranged for by the manufacturer.
- 7. SEQUENCE OF PROCEDURES:** Read paragraph No. 3
- 8. DATE OF ISSUE:** In Jevíčko on July 08, 2004

Ing. Jaroslav Sedlák – Technical Department Manager
MarS a.s. Jevíčko

Stamp and signature:

